

Honda 2021 JAZZ Crankshaft (CKP) Sensor Matching Value Learning

Tested Model: HONDA JAZZ HYBRID 2021

Function Description:

For Honda models, after repairing the misfire or replacing the CKP sensor, you need to perform this function to write the new crankshaft (CKP) sensor matching value to the ECM/PCM.

Execution Conditions:

- Connector connected and ignition switch ON
- In P gear
- Engine coolant temperature: over 75 [°C] (HEV system engine coolant temperature: over 80 [°C])
- ATF temperature: over 45 [°C]
- Before starting the engine, the hybrid vehicle must be switched to the maintenance mode.

Procedure:

1. On a PAD 5, choose [Local Diagnose], and then choose [Honda] for testing.


X-431 PAD5 V8.00.016

| | | | | |
|---|---|--|---|--|
|  Intelligent Diagnose |  Local Diagnose |  Remote Diagnose |  New Energy Diagnose |  Special Function |
|  Online Programming |  Toolbox |  Software Update |  Engine Health Test |  X-431 Diagnosis Kit |
|  Know Your Customer |  Mall |  Launch Academy |  User Info |  更多 (测试) |


Local Diagnose SN: 989347213175


Automotive HD Motorcycle IMMO EV Battery Pack

| | | | | | | |
|---------|--|--|--|--|--|---|
| All | VINScan Service | | Diagnostics for Honda <small>by LAUNCH</small> | Diagnostics for Mitsubishi <small>by LAUNCH</small> | Diagnostics for Acura <small>by LAUNCH</small> | Diagnostics for Demo <small>by LAUNCH</small> |
| America | VINScan Service | | Honda | Mitsubishi | Acura | Demo |
| Europe | VINScan Service | | Honda | Mitsubishi | Acura | Demo |
| Asia | Diagnostics for EOBD/OBDII <small>by LAUNCH</small> | Diagnostics for Alfa Romeo <small>by LAUNCH</small> | Diagnostics for Audi <small>by LAUNCH</small> | Diagnostics for Bentley <small>by LAUNCH</small> | Diagnostics for Brilliance SRM <small>by LAUNCH</small> | Diagnostics for Bugatti <small>by LAUNCH</small> |
| China | Diagnostics for Buick <small>by LAUNCH</small> | Diagnostics for BYD <small>by LAUNCH</small> | Diagnostics for Cadillac <small>by LAUNCH</small> | Diagnostics for Chery <small>by LAUNCH</small> | Diagnostics for CheryEV <small>by LAUNCH</small> | Diagnostics for Chevrolet <small>by LAUNCH</small> |




2. Click [16PIN DLC], and then choose the region to automatically identify the car model. For this test, choose the [General] region.







3. Confirm the vehicle information, and then click OK.




4. Choose the engine system and click [ENTER].




5. Choose [Special Function].




6. Choose [Crank (CKP) Pattern].




7. Choose [Crank (CKP) Pattern Clear] to clear the crankshaft (CKP) sensor matching value data stored in the ECM/PCM.




8. View the function description and click OK.




9. Clearing...Please wait.




10. Start the engine as prompted and then click OK. Before starting the engine, the hybrid vehicle must be switched to the maintenance mode.




11. Turn off the ignition switch as prompted, and then click OK.




12. Turn on the ignition switch as prompted, and then click OK.




13. Wait for 30s.




14. The crankshaft (CKP) sensor matching value data in the ECM/PCM has been cleared. Click OK.




15. Choose [Crank (CKP) Pattern Learning] to write the new crankshaft (CKP) sensor matching value into the ECM/PCM.




16. After checking that all the test conditions are met, click OK.




17. The software checks whether the test conditions are normal.




18. Turn off the ignition switch as prompted, and then click OK.




19. Turn on the ignition switch as prompted, and then click OK.




20. Start the engine as prompted and then click OK. Before starting the engine, the hybrid vehicle must be switched to the maintenance mode.




21. Depress the accelerator pedal to increase the engine speed to over 3500 RPM.



22. Release the throttle and click OK.



23. The new crankshaft (CKP) sensor matching value has been written to the ECM/PCM, and the crankshaft (CKP) sensor matching value learning is completed.



Statement:

The content of this document is copyrighted by LAUNCH TECH CO., LTD., and no individual or organization may quote or reprint it without consent.