

Instructions for Service Reset

Tested Model:


Range Rover(L460)2023, VIN code: SALKABFU3PA04****.

[Background of function execution]



This function is used when engine oil, check and service information needs to be reset



[Instructions]

1. Turn ignition switch ON, connect to Launch X431 PAD VII connector, select LandRover model software (V34.85 version or above), go into menu and select Automatically Search:







2. Operator information can select online mode to perform diagnosis. After entered the interface, select "DoIP protocol for vehicle communication", select Special Function -> common Special Function -> Reset in sequence after log in






- Click Service Message Reset, it would pop out battery voltage >12.0V, if selected No, it would prompt relevant voltage specification should be met, click OK to return previous menu (service message reset interface); if selected YES, it would prompt to turn on ignition switch, click OK to enter next step





4. Displayed service message reset menu, if click return to return step 3 (service message reset interface), click full service reset. It displayed operation successful, click OK to return step 3 (service message reset).



Statement:

The content of this document is copyrighted by LAUNCH TECH CO., LTD., and no individual or organization may quote or reprint it without consent.