# BMW 525Li Driver Seat Standardisation

**Function description:** seat standardisation

**Supported products:** Launch PRO or PAD series comprehensive diagnostic equipment

**Tested model:** BMW 525Li VIN: LBVKY1105JSR5**** (See the following figure)



The SMFA (Seat module, driver) reports the DTC 8029CA "SMFA: Seat Position Not Sent Due To Missing Or Invalid Calibration". (See the following figure.)

# Procedure:

1. Access [SMFA (Seat module, driver)] and choose [Fault Guidance]. (See the following figure.)



2. Choose [Seat Standardisation, Driver's Seat] in [Special Function]. (See the following figure.)

3.  Click [Operate]. (See the following figure.)



4.  The prompt "Control unit is identified: Driver's Seat Module (SMFA). Please wait!" is displayed. (See the following figure.)

5. Relevant faults are stored in the SMFA control unit. Driver's seat standardisation must be performed. Click [Continue]. (See the following figure.)



6. Note the prompts regarding seat standardisation. Press [Continue] to start standardisation. (See the following figure.)

7. Seat standardisation is active. Please wait. (See the following figure.)



8. Standardisation is finished. (See the following figure.)

9. Seat standardisation setting is successful. (See the following figure.)

BMW V51.65 > Automatically Search > SMFA (Seat module, driver)      ↑112 b/s  ↓120 b/s  12.15V

& Execution Steps &

Seat Standardisation Was Successful.

Continue

10. Exit the service function. (See the following figure.)

BMW V51.65 > Automatically Search > SMFA (Seat module, driver)      ↑0 b/s  ↓0 b/s  12.15V

& Execution Steps &

Service Function Ended.

Continue

11. There is no DTC in the system. (See the following figure.)



## Statement:

The content of this document is copyrighted by LAUNCH TECH CO., LTD., and no individual or organization may quote or reprint it without consent.