LAUNCH

VW

Basic_Electromechanical_Parking_Brake_Control_Unit_Settings_ Golf _2015

Tested models:

Volkswagen Golf 2015

Volkswagen Golf fault code:

C10E254 electromechanical parking brake control unit-no basic settings, need to perform this function.

Issue description：

Electronic parking brake failure, as shown below:

Operation Guide:

1. X-431 remote diagnosis, read the fault code of 03 brake electronic device as follows; C10E254 electromechanical parking brake control unit-no basic setting, the state is active/static, the fault code cannot be cleared, as shown in Figure 1:


Figure 1

2. Select "04 Basic Settings" option.

Figure 2

3. Select "Electric-mechanical parking brake function test", as shown in Figure 3:



Figure 3

4. Click "Adjust" option, as shown in Figure 4:

Figure 4

5. The basic setting status is running, as shown in Figure 5:


Figure 5

6. Read the fault code of 03 brake electronic device as follows: C10E254 electromechanical parking brake-no basic settings, the state is Passive/Abiogenesis, as shown in Figure 6:


Figure 6

7. Click "Yes" to clear the fault memory, as shown in Figure 7:

Figure 7

8. Clear the fault code has been completed, click "Yes" to read the fault code(DTC) again, as shown in Figure 8.


Figure 8

9. There is no fault code of C10E254, as shown in Figure 9:

Figure 9

10. The instrument has no fault light, as shown in Figure 10:

Figure 10

The end.