2020 BMW 740Li Right Rear Light Programming

Function description: Replace the right rear light

Supported products: Launch PAD 3, PAD 5, PRO5 with programming diagnostic equipment

Tested model: 2020 BMW 740Li, VIN: WBA7T2106LCE68****

The DTCs are as follows:

Procedure:

1. Choose [Coding/Program], as shown in Figure 1.

Figure 1

2. Choose [Coding], as shown in Figure 2.

Figure 2

3. Confirm the vehicle information and then choose [NEXT], as shown in Figure 3.

Figure 3

4. Choose the corresponding system [RLMIR (Inner right rear light module)], as shown in Figure 4.

Figure 4

5. To continue coding, choose [YES], as shown in Figure 5.

Figure 5

6. Choose the coding configuration file [S15A-21-11-564*], as shown in Figure 6.

Figure 6

7. Click [Continue], as shown in Figure 7.

Figure 7

8. Coding is successful. Click OK to exit, as shown in Figure 8.

Figure 8

Statement: