# LAUNCH

VW Report_Fault_Code_P160900_Crash Shut-off_Triggered Volkswagen_Santana_2018

1. Enter the diagnostic system to do a quick test.

|	
Show Menu	🏠 🖨 ↪
VW V28.66 > Menu	🔋 12.67V
Health Report	System Scan
System Selection	Special Function
Online Function	VW Crafter (LT3) Light Trucks
Guided Functions	ADAS Calibration
Procedures	

VW

2. Read the steering system has fault code P160900.

Diagnostic Trouble Code			🏠 🖨 ↪
VW V28.66 > Health Report			🔋 12.69V
44 Steering Assistance	1	∧	**Enter**
P160900 Crash Shut-off Was Triggered		Active/Static	🔍
01 Engine Control Module 1		Normal	**Enter**
02 Transmission Control Module		Normal	**Enter**
03 Brakes 1		Normal	**Enter**
09 Central Electrics		Normal	**Enter**
15 Airbag		Normal	**Enter**

VW 2018
VIN LSVNY4BR0JN128922

| Report | Help | Compare Results | Clear DTCs |

LAUNCH

3. To log in safely, enter the login code 20103.

4. Enter '44 Steering Assistance' and select the 'Resetting Of All Adaptation Values'.

5. Click adjust option.

Function Name	Parameter Value	Unit
ly	Finished Correctly	
Resetting Of All Adaptation Values	$0317	
Reset Of Adaption Values	All Adaption Values	

Basic Setting

VW V28.66 > Health Report>44 Steering Assistance   12.81V

ADJUST	Stop

VW 2018
VIN LSVNY4BR0JN128922

6. After the system displays correctly, check and read the fault code again

Diagnostic Trouble Code

VW V28.66 > Health Report>44 Steering Assistance   12.72V

No Fault Code.

Freeze Frame	Help	Code Search

VW 2018
VIN LSVNY4BR0JN128922   Report

LAUNCH

7. Finally, if re-reading the whole system successfully completed without any fault code, then it is success.

Diagnostic Trouble Code		
VW V28.66 > Health Report		12.80V
01 Engine Control Module 1	Normal	Enter
02 Transmission Control Module	Normal	Enter
03 Brakes 1	Normal	Enter
09 Central Electrics	Normal	Enter
15 Airbag	Normal	Enter
17 Dash Board	Normal	Enter
44 Steering Assistance	Normal	Enter

VW 2018
VIN LSVNY4BR0JN128922   Report   Help   Compare Results   Clear DTCs

The end.