

P1702 Internal Control Module Memory Check Sum Error

DTC Detecting Condition and Trouble Area

DTC Detecting Condition	Trouble Area
An internal TCM fault is detected by TCM (1 driving cycle detection logic)	TCM

NOTE

DTC P1702 can never be cleared once it has been set.

- 1) Ignition switch OFF.
- 2) Replace TCM.
- 3) Repeat "A/T System Check ".

LAUNCH