

B1330 B1335 IMPACT SENSOR

DTC DESCRIPTION


The detecting system for front crash consists of the SRSCM and two Front Impact Sensors (FIS). The SRSCM sets above DTC(s) if it detects wrong FIS is used.

DTC	FAULT DESCRIPTION
B1330	FRONT IMPACT SENSOR [DRIVER] WRONG ID
B1335	FRONT IMPACT SENSOR [PASSENGER] WRONG ID

DTC DETECTING CONDITION

DTC	Condition	Probable cause
B1330 B1335	<ul style="list-style-type: none"> Wrong Front Impact Sensor(FIS) SRSCM Malfunction 	<ul style="list-style-type: none"> Front Impact Sensor(FIS) SRSCM

SCHEMATIC DIAGRAM



TERMINAL & CONNECTOR INSPECTION

Refer to the DESCRIPTION in this TROUBLESHOOTING section.

INSPECTION PROCEDURE

If above DTC is detected replace the Front Impact Sensor.