Configuration of the siren

This function is intended to set the configuration of the siren.


Now take XC90 2007 30797802 AA (ECU Diagnostic Part Number) as an example to illustrate the operation:

Note: The highlight item in the figure indicates corresponding action.

1. step 1: XC90

SELECT MENU				
V70 XC(-00)				
V70 XC(01-)/XC70(-07)				
XC70 (08-)				
₹90				
XC90				
XC90 V8				
С30				
C70 (06-)				
PAGE UP		PAGE DOWN		
HOME	BACK	PRIMI	HELP	
Start)		P 0:	=== 15:23	

2. step 2: select year




3. step 3: select UEM

SELECT MENU				
UEM(Up electrical module)				
REM(Rear electrical module)				
DIM(Driver information module)				
PDM(Passenger door module)				
PSM(Power seat module)				
DDM(Driver door module)				
CCM(Climate control module)				
PHM(Phone module)				
PAGE UP		PAGE DOWN		
HOME	BACK	PRIMI	HELP	
Start		¥ ×	₩ 15:24	

 step 4: Select Special Function.

If you can't find the Special Function menu, it means the function has not been developed on your vehicle. Please record the VIN (Vehicle Identification Number) and Version Information (can be read by X431 with the function: Reading off control module ID) and email to Launch (x431@cnlaunch.com). We may work out a solution on how to solve the problem.



5. step 5: Select Configuration of the siren




6. step 6:

The information of Configuration of the siren:

Note! When the siren has been replaced, a configuration has to be done in order to make the siren work properly.

Ignition on

Ensure that no diagnostic trouble codes(DTCs) have been stored.



7. step 7:

Select OK, it will send command to ECU and start programming. If configuration succeeds, it will display: Configuration Completed.

Otherwise it displays: Configuration Failed. In the case, please try again.

