

## BMW 525Li Sunroof Normalization


**Function description:** sunroof normalization

**Supported products:** Launch PRO or PAD series comprehensive diagnostic equipment

**Tested model:** BMW 525Li VIN:LBV5S310XFSK3\*\*\*\* (see the following figure)




The FZD system reports the following DTC: 030215 SHD: No Normalization. (See the following figure.)




## Procedure:


1. Click the special function [Normalise Slide/Tilt Sunroof]. (See the following figure.)




2. Click [F1. Perform Standardisation Procedure]. (See the following figure.)




3. Normalization setting in process. (See the following figure.)




4. Confirm the ignition switch status. (See the following figure.)




5. Normalization setting is ended successfully, and no DTC appears. (See the following figure.)



6. The service function is finished. (See the following figure.)



7. Access the FZD system to read DTCs. There is no DTC.



### Statement:

The content of this document is copyrighted by Shenzhen Launch Tech Co., Ltd., and no individual or organization may quote or reprint it without consent.