

FIAT Pulse Service Information Reset (Service Lamp Reset) Method


Supported equipment: Launch's full range of comprehensive diagnostic equipment

Current equipment: PAD 5

Function description: After maintenance is completed for FIAT, service information reset is required.

Tested model: 2023/Fiat/Pulse, VIN: 9BD363B22PYZ*****

1. On a PAD 5, choose [Local Diagnose] and then [FIAT] to test.



Local Diagnose

Enter the model name

VIN scanAllCommonAmericanEuropeanAsianChineseCan Bus Pin DetectionPurchase

Diagnostics for

ABARTH

by LAUNCH

Diagnostics for

ALFA ROMEO

by LAUNCH

Diagnostics for

CHRYSLER

by LAUNCH

Diagnostics for

DODGE

by LAUNCH

Diagnostics for

FIAT

by LAUNCH

Diagnostics for

JEEP

by LAUNCH

Diagnostics for

LANCIA

by LAUNCH

Vehicle Version Information

HomePrintShare

FIAT V38.50

Introduction



ECU Coverage:

Basic Functions Include:


Special functions include:

Vehicle CoverageOK


2. Choose [Automatically Search] to identify car models automatically. After the car model is successfully identified, choose OK.




3. Choose [Yes] to unlock the SGW.




4. Choose [North America] for the region.




5. Input the login user name and password, and click OK.




6. Unlocking is successful. Click OK.





7. Click [Smart Detection] to scan the entire vehicle systems.




8. Click [IPC (Instrument Panel Cluster)] to access the system.




9. Click [Special Function] and click OK.




10. Choose [Misc Function].




11. Choose [Reset Service Information].




12. Click OK.



13. Click OK.



14. Click OK. Program execution is completed.



Statement:

The content of this document is copyrighted by LAUNCH TECH CO., LTD., and no individual or organization may quote or reprint it without consent.