

# B1A33 UNIVERSAL GARAGE DOOR SWITCH 2 STUCK

- 1). When Monitored:  
With the ignition on.
- 2). Set Condition:  
The Electronic Overhead Module detects the UGDO switch in the closed position for more than 2 minutes.

Possible Causes
1. ELECTRONIC OVERHEAD MODULE



## Diagnostic Test

- 1). REPLACE THE ELECTRONIC OVERHEAD MODULE  
When this code is set, the Electronic Overhead Module must be replaced.  
Repair  
Replace the Electronic Overhead Module in accordance with the Service Information.  
Perform BODY VERIFICATION TEST - VER 1.