

2015 Porsche Cayenne A221 Service Lamp Resetting Method

| Product Model | Date | Number |
|----------------|----------|--------|
| X431Pro series | 20160331 | — |

Vehicle coverage:

- Porsche Cayenne A221, 2015, VIN=WP1AG2926FLA*****, as shown in Figure 1 and Figure 2.



Figure 1



Figure 2

Procedure:

- 1). Turn on the ignition switch.
- 2). Choose Service Lamp Reset V10.42.
- 3). Choose PORSCHE (Porsche). See Figure 3.




Figure 3

- 4). Choose Software Reset. See Figure 4.




Figure 4

5).Choose Automatic Scanning. See Figure 5.




Figure 5

6).Choose Cayenne. See Figure 6.




Figure 6

7). Choose Oil Reset. See Figure 7.




Figure 7

8). Enter the current date. See Figure 8.




Figure 8

9). Enter the current service date as required, such as 20160331. See Figure 9.




Figure 9

10). Click OK. The message "The service period has been successfully reset" is displayed. The vehicle service message disappears. See Figure 9.



Figure 9

11). Turn off the ignition switch and exit the software. Service lamp resetting is complete.