

Cayenne Diesel 2016 Urea Reset

Function description: Cayenne diesel 2016 urea reset

Supported products: Launch's full range of comprehensive diagnostic equipment

Tested model: Cayenne diesel 2016

Procedure:


1. The urea pump on a Cayenne 2016 is faulty and is replaced with a brand new urea pump.




2. As the urea pump assembly integrates a urea level sensor and a urea temperature sensor, the urea level needs to be initialized after the urea pump is replaced with a new one.




3. Use 431PADV to enter the Porsche diagnostic software and click [System List].




4. Select the engine module and click [Enter].




5. Click [Special Function].




6. Choose [Reducing Agent System].




7. Choose [Reset Reducing Agent Tank Fill Level]. Note: Before the reset, the vehicle urea tank needs to be filled with urea.




8. Click "Next".



9. Click OK to reset.



10. Reset is successful. Click OK, and the urea reset is completed.



Statement:

The content of this document is copyrighted by Shenzhen Launch Tech Co., Ltd., and no individual or organization may quote or reprint it without consent.