

VW Tiguan 76 Parking Aid System Online Coding

Function description: The 76 parking aid system of VW Tiguan has the following DTC: U101300 Control Module Not Coded. It is necessary to perform the online coding function.

Supported products: Launch PRO or PAD series comprehensive diagnostic equipment

Tested model: VW Tiguan 2017, VIN: LSVUC20T9H2***** (see the following figure)



Procedure:

1. The 76 parking aid system has the following DTC: U101300 Control Module Not Coded. (See the following figure.)




Figure 1

2. Access [Online Function] and choose [Online Coding]. (See the following figure.)




Figure 2

3. Choose [Single System Mode]. (See the following figure.)




Figure 3

4. Choose [76 Parking Aid] and click [Click To Code]. (See the following figure.)




Figure 4

5. Choose [Possible Code01]. (See the following figure.)




Figure 5

6. Click OK to modify the code. (See the following figure.)




Figure 6

7. Coding has been successfully carried out. Click OK. (See the following figure.)




Figure 7

8. Save the fault report. The 76 parking aid system has no DTC. (See the following figure.)




Figure 8

Statement:

The content of this document is copyrighted by Shenzhen Launch Tech Co., Ltd., and no individual or organization may quote or reprint it without consent.