2014 Benz Chassis 212 Throttle Adaptation Method

Product Model	Date	Number
X431Pro series	20160107	

Vehicle coverage:

• Benz, 2014, VIN=LE4HG4HB4DL1****

Function Description:


After the throttle is cleaned, this function must be performed to clear throttle memory values to stabilize the idle speed.

Prerequisites:


- Ignition switch is ON.
- Internal combustion engine is stationary for at least one minute.
- The accelerator pedal is not operated.
- No CAN fault exists in the traction system in the control unit
- Coolant temperature is between 5°C-100°C.
- Intake temperature is below or equal to 40℃.

Procedure:


1). Choose MERCEDES V48.20 or later version.




2). Choose Automatically Search




3). Check that the displayed VIN is correct.




4). Choose system selection.




5). Choose ECM - internal combustion engine M271EVO engine control module (SIM271DE20) (N3/10).




6). Choose special function.




- 7). Choose learning process.
- 8). Choose learning throttle valve stop.



- 9). Choose throttle stop position learning.
- 10). Click OK. A message is displayed, asking that throttle learning must meet the related value requirements.
- 11). Check that the engine status, accelerator pedal position, coolant temperature, and throttle intake temperature reach the specified values. Then click OK.
- 12). Click F3 to start throttle learning. Note the message "Learning in process...Please wait." See Figure 5.



13). After about 60s, a message prompting that learning is complete is displayed. See Figure 6.



14). Click OK. After about 10s, the system returns to the menu page. Turn off the ignition switch. The operation is complete.

Launch is always making efforts for the pursuit of good functions and satisfaction of customer requirements. Focus on Launch. You can make progress everyday!



I A THE STATE OF T