

GM Chevrolet Suburban 2021 Heated Oxygen Sensor Heater Resistance Learned Values Reset


Supported equipment: Launch's full range of comprehensive diagnostic equipment

Current equipment: PAD 5



Function description: This function needs to be executed after the heated oxygen sensor is replaced.

Tested model: 2021 GM Chevrolet Suburban, VIN: 1GNSKDKD9MR*****



1. It is necessary to stop the vehicle before performing this function. On a PAD 5, choose [Local Diagnose].





2. Choose [GM] to test.





3. Choose [Automatically Search] to identify car models automatically.





4. Operate according to the prompt “Turn Ignition ON (Turn The Key To On Position. For Push-Start Vehicle, Please Long Press The Start Button For 5-10s To Turn Ignition On)”.




5. Click [ECM] to access the system.




6. Choose [Special Functions] and then choose [Reset Functions].



7. Choose [Heated Oxygen Sensor Heater Resistance Learned Values Reset].



8. Before the function reset, the status is “None”. Click [Reset].



9. The status changes to “Reset”. The reset is successful.



The content of this document is copyrighted by LAUNCH TECH CO., LTD., and no individual or organization may quote or reprint it without consent.