

# VW Tiguan 76 Parking Aid System Online Parametric Configuration

**Function description:** The 76 parking aid system of VW Tiguan has the following DTC: B200500 Data Record Invalid. It is necessary to perform the online parametric configuration function.

**Supported products:** Launch PRO3S+V2.0, PRO3S+V3.0, PRO3S+V5.0, PADIII, PADV, PADVII, and other diagnostic equipment that support the online parametric configuration” function

**Tested model:** VW Tiguan 2017, VIN: LSVUC20T9H2\*\*\*\*\* (see the following figure)



## Procedure:

1. Save the fault report. The 76 parking aid system has the following DTC: B200500 Data Record Invalid. (See the following figure.)




Figure 1

2. Choose [Online Function]. (See the following figure.)




Figure 2

3. Choose [Online Parametric Configuration]. (See the following figure.)



Figure 3

4. Read the disclaimer carefully and click OK. (See the following figure.)




Figure 4



7. Choose the first optional file and click OK. (See the following figure.)




Figure 7

8. Turn off the ignition switch, wait for 30s, and then turn on the ignition switch. Then, click OK. (See the following figure.)




Figure 8

9. Compare the data before and after update. (See the following figure.)

Feature	Before Update	After Update
System Description:	J446	J446
Engine Code:	PDC 4 Kanal	PDC 4 Kanal
VIN Code:		
FAZIT Identification:	4HK-00118.10.17P8010860	4HK-00118.10.17P8010860
Serial Number:	00030841921728101890	00030841921728101890
ECU Programming Information	Program Available Programmable	Program Available Programmable
ECU Data Programming Information	EEPROM Data Programmable EEPROM Data Not Modified Last Data Record Download Fault: General Fault EEPROM Valid Data	EEPROM Data Programmable EEPROM Data Not Modified Last Data Record Download Fault: General Fault EEPROM Valid Data

大众 途观L 2017  
VIN LSVUC20T9H4

Figure 9

10. The DTC B200500 Data Record Invalid is cleared. (See the following figure.)

Diagnostic Trouble Code

VW V29.02 > Online Function > Online Parametric Configuration 12.63V

**U101300** Control Module Not Coded

Active/Static

Freeze Frame    Help    Code Search

大众 途观L 2017  
VIN LSVUC20T9H4

Report

Figure 10

**Statement:**

The content of this document is copyrighted by Shenzhen Launch Tech Co., Ltd., and no individual or organization may quote or reprint it without consent.