

Resetting Auto T/A Values

Applicable Models

All Hyundai and Kia models

Function Description

This function is used to reset the transaxle values of Hyundai and Kia. This function is performed when the gearbox related parts are replaced.


Conditions

The ignition switch is ON and the engine is turned off.


Procedure

Take Carens (KY) 2024 as an example:


1. After entering the gearbox system, choose [Resetting Auto T/A Values] under the special functions, as shown in the figure.




2. The program prompts the function conditions. Click OK.



3. The program confirms again whether to execute.



4. The program is executed successfully.



Attention

A. After this function is executed, you need to exit the diagnostic software, turn off the key, wait for more than 15 seconds, and then turn on the key.