

Benz E300L Service Reset

Function description: service lamp reset

Supported products: Launch PRO or PAD series comprehensive diagnostic equipment

Tested model: Benz E300L VIN: LE4ZG8DB5ML70**** (see the following figure)



The instrument cluster prompts that the next service A will be after 343 kilometers.
(See the following figure.)



Procedure:

1. Choose [IC - Instrument Cluster] to access the system. (See the following figure.)

Diagnostic Trouble Code

MERCEDES-BENZ V50.36 > 213>213.183 - E 300 Sedan (long wheelbase)>Health Report 12.17V

N72/1 (Upper control panel control unit)	Normal	Enter
N72/4 (Left lower control panel)	Normal	Enter
N72/5 (Right lower control panel)	Normal	Enter
IC - Instrument Cluster	Normal	Enter
TPAD - Touchpad	Normal	Enter
MTAS - Mobile Phone Cradle	Normal	Enter
AC - Air Conditioning	Normal	Enter

213.183 - E300 Sedan (long wheelbase) 2021
VIN LE4ZG8DB5M1

Report Help Compare Results Clear DTCs


2. Choose [Actuation Test]. (See the following figure.)




3. Choose [Maintenance]. (See the following figure.)



4. Choose [Confirmation of general maintenance]. (See the following figure.)



5. Click [Continue]. (See the following figure.)



6. Click [F2: Confirmation of general maintenance]. (See the following figure.)

Notes

MERCEDES-BENZ V50.36 > 213>213.183 - E 300 Sedan (long wheelbase)>Health Report>IC - Instrument Cluster>Actuation Test>Maintenance>Conf... 11.78V

Workshop code

5380

Service code

A

Note
 F2:Confirmation of general maintenance
 The performance of all maintenance items currently due is being confirmed.
 Status of actuation :
 NOT PERFORMED

1

EXIT F2 Continue

213.183 - E300 Sedan (long wheelbase) 2021
 VIN LE4ZG8DB5M

Information


MERCEDES-BENZ V50.36 > 213>213.183 - E 300 Sedan (long wheelbase)>Health Report>IC - Instrument Cluster>Actuation Test>Maintenance>Conf... 11.91V

Name	Value	Specified value
Summary for service booklet		
Service code	A	
Workshop code	5380	
Remaining time	153	
Remaining distance	342.79	
After confirmation of general maintenance some actual values are no longer available.		


Back Continue

213.183 - E300 Sedan (long wheelbase) 2021
 VIN LE4ZG8DB5M

7. Updating the data...(See the following figure.)



8. Recalculating...(See the following figure.)



Notes

MERCEDES-BENZ V50.36 > 213>213.183 - E 300 Sedan (long wheelbase)>Health Report>IC - Instrument Cluster>Actuation Test>Maintenance>Conf... 11.70V

1

Oil quality

229.52

Status of associated actual values

1

Remaining distance until next service due

10000.46 km

EXIT F2 Continue

213.183 - E300 Sedan (long wheelbase) 2021
VIN LE4ZG8DB5M

9. Service reset is completed. The instrument cluster prompts that the next service B0 is after 365 days. (See the following figure.)



Statement:

The content of this document is copyrighted by Shenzhen Launch Tech Co., Ltd., and no individual or organization may quote or reprint it without consent.