

Maybach S480 Service Reset


Function description: service reset

Supported products: Launch PRO or PAD series comprehensive diagnostic equipment

Tested model: Maybach S480 VIN: W1K6X6BB7MA05**** (see the following figure)




The instrument cluster prompts that the next service A1 will be after 187 kilometers. (See the following figure.)




Procedure:


1. Choose [IC - Instrument cluster] to access the system. (See the following figure.)





2. Choose [Actuation Test]. (See the following figure.)




3. Choose [Maintenance]. (See the following figure.)











4. Choose [Confirmation of general maintenance]. (See the following figure.)



5. Follow the prompts to continue. (See the following figure.)



Notes    

MERCEDES-BENZ V50.36 > 223>223.961 - Mercedes Maybach S 450 4MATIC / Mercedes Maybach S 480 4MATIC>...   1.90 kb/s  1.65 kb/s  11.82V

187 km

Days until next service date

242


Workshop code






D3G0





Service code





A1

EXIT F2 Continue

Mercedes-Benz 223.961 - Mercedes-Maybach S 450 4MATIC/Mercedes-Maybach S 480 4MATIC
VIN W1K6X6BB7MA 

Notes    

MERCEDES-BENZ V50.36 > 223>223.961 - Mercedes Maybach S 450 4MATIC / Mercedes Maybach S 480 4MATIC>...   1.89 kb/s  1.63 kb/s  11.82V

Workshop code

D3G0


Service code






A1





Note
F2:Confirmation of general maintenance
The performance of all maintenance items currently due is being confirmed.
Status of actuation :
NOT PERFORMED





1

EXIT F2 Continue

Mercedes-Benz 223.961 - Mercedes-Maybach S 450 4MATIC/Mercedes-Maybach S 480 4MATIC
VIN W1K6X6BB7M 







Information    





MERCEDES-BENZ V50.36 > 223>223.961 - Mercedes Maybach S 450 4MATIC / Mercedes Maybach S 480 4MATIC>...   178 b/s  142 b/s  11.82V




| Name | Value | Specified value |
|---|--------|-----------------|
| Summary for service booklet | | |
| Service code | A1 | |
| Workshop code | D3 | |
| Remaining time | -- | |
| Remaining distance | 187.00 | |
| After confirmation of general maintenance some actual values are no longer available. | | |

[Back](#) [Continue](#)

Mercedes-Benz 223.961 - Mercedes-Maybach S 450 4MATIC/Mercedes-Maybach S 480 4MATIC
VIN W1K6X6BB7MA [redacted]


     

Information    

MERCEDES-BENZ V50.36 > 223>223.961 - Mercedes Maybach S 450 4MATIC / Mercedes Maybach S 480 4MATIC>...  134 b/s  107 b/s  11.82V

| Name | Value | Specified value |
|---|-------|-----------------|
| Summary for service booklet | | |
| Service code | A1 | |
| Workshop code | | |
| Remaining time | | |
| Remaining distance | | |
| After confirmation of general maintenance some actual values are no longer available. | | |







Notes

 The data are being updated. Please wait...
[24]

[END SESSION](#)

[Back](#) [Continue](#)

Mercedes-Benz 223.961 - Mercedes-Maybach S 450 4MATIC/Mercedes-Maybach S 480 4MATIC
VIN W1K6X6BB7M [redacted]

6. F2: Confirmation of general maintenance is successful. (See the following figure.)

Notes

MERCEDES-BENZ V50.36 > 223>223.961 - Mercedes Maybach S 450 4MATIC / Mercedes Maybach S 480 4MATIC>... 134 b/s 107 b/s 11.82V

Workshop code

D3

Service code

A1

Note
F2: Confirmation of general maintenance
The performance of all maintenance items currently due is being confirmed.
Status of actuation :
SUCCESSFUL

1

EXIT F2 Continue

Mercedes-Benz 223 961 - Mercedes-Maybach S 450 4MATIC/Mercedes-Maybach S 480 4MATIC
VIN W1K6X6BB7M...

7. The instrument cluster prompts that the next service BJ will be after 10000 kilometers. (See the following figure.)



Statement:

The content of this document is copyrighted by Shenzhen Launch Tech Co., Ltd., and no individual or organization may quote or reprint it without consent.